## FIELD INSPECTION REPORT

District: Muzafferpu Date of Inspection: 05/12/2020 Length (km): 3.186 Division: Muz - East - 2 Name of the Road: Minapur PWD Road to Wharar MAINTENANCE Scheme/Programme: Road Id No .: Package No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked SI. No. 1. Pavement S/U Road Junction condition a) S/U N.A. b) Condition of Surfacing S/U N.A. Riding Quality c) S/U N.A Road Camber d) Whether free from defects such as visible cracks, exposed Yes/No N.A c) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) N.A f) Yes/No Compaction of flank/slope & raincuts if any N.A g) 2. Cross Drainage Condition of head walls in Hume pipe culverts including its painting S/SRI/U N.A a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts NID b) S/SRI/U NIA Condition of railings/slab/approach for Bridges c) Road Furniture 3. Information sourd

Overall Rating: - Work Not started

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

a)

4.

a)

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

> .12.2020 (Signature)

Yes/No

Zixid

NAME: Kamta Pd. Singl

Compliance History

Status of ATR's & any others

DESIGNATION: JE minapun

Scanned with CamScanner