

# FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Muzaffarpur
Division :	R.W.D Muz. East-1	Length (km):	0.750km
Name of the Road:	NH 28 to Mashaulla hundi nobhotehua science college Nulak		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: KUNIL KUMAR  
DESIGNATION: J.E

*Kunil Kumar*  
3/12/2020  
J.E

*[Signature]*  
3/12/20  
(Signature)  
E.E