FIELD INSPECTION REPORT

	nspection:	3/12/2000 District: MV20 Her	
Division	: R.W.	D MUZ costy Length (km): 2.3 km	
Scheme!	tne Road: The	MAINTENANCE Length (km): 2.3 x Length (km): 2.3 x Length (km): 2.3 x MAINTENANCE	too dail piv los
Package	No:		Rockha.
Package No.: Status of the Project: Ongoing/Completed/Under Maintenance			
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be checked	
1.	Pavement	and the checked	Remarks
a)	Road Junction condition		
b)		\	
	Condition of Surfacing		S/U
c)	Riding Quality		~811 ~51'
d)	Road Camber		~5 1'
e)	Whether free aggregates in c	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/I		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes No is TU
4.	Compliance History		
a) 5	Status of ATR's	s & any others	No.
verall Ra	ating :	Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	0.05

Unsatisfactory (U)

NAME: KUNIL KUMAR Julkhum ' (Signature)

DESIGNATION: JEE