

FIELD INSPECTION REPORT

Date of Inspection : 3/12/20	District: Muzaffarpur
Division : Muzaffarpur Garh-1	Length (km):
Name of the Road: Grijas Pakhi sadak to existing tole	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S/U
b)	Condition of Surfacing	S/S/U
c)	Riding Quality	S/S/U
d)	Road Camber	S/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This road is submerged in Flood from ch. 1600 to 2100. Between above chainage the road is contoured on the bank of beya river. For long term safety of road protection work required between above chainage.

(Signature)

NAME:

DESIGNATION:

3/12/20
JL