


FIELD INSPECTION REPORT

Date of Inspection : 03.12.20		District: Muzaffarpur
Division : RWD. Muz. West		Length (km): 3.70 km
Name of the Road: D Thikha Patel Chowk Se Tahagirpur Tola Hote hue Thikha Begos		
Scheme/Programme: MAINTENANCE New Maint.		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. C.C. NO PROVISION	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement) C.C. NO PROVISION	Yes/No
g)	Compaction of flank/slope & raincuts if any Compaction yes Rain cuts No	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	140.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

 03.12.20
 (Signature)
 3/12/20
 J-C

NAME:

DESIGNATION: