FIELD INSPECTION REPORT

Date of Inspection: 51272			District: Muzofforfon	
Division: Muzaffarfus east 2			Length (km): 1.25 K-19	
Name of	the Road: 3	with mathin ma	ainroad to pathonetes	
Scheme/	Programme:	MAINTENANCE	New Maintenere Policy	
			Road Id No.:	
	f the Project:		I/Under Maintenance	
	a case of:		Jp gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			A S/U
b)	Condition of Surfacing			A S/U
c)	Riding Quality			ent
d)	Road Camber			SAL
c)	Whether free from defects such as visible cracks, exposed Yes/No N			
f)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No MA
g)	Compaction of flank/slope & raincuts if any			Yes/No NA
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U-
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	stones/Payement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME: pardyanaty chandhay

:

DESIGNATION: JE POY MAJOR -