## FIELD INSPECTION REPORT

Date of 1	inspection:- 5. a.a. Di	istrict:- Sheohar.		
Division:-RWD, Works Div. Sheohar Length (km):- 5.36		nok m		
Name of	the Road: - Somul High School	to Bom & Tag	dishbest	
Scheme/	Programme:- MAINTENANCI	E		
Package No.:- Road Id No.:				
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition		S/U	
<b>b</b> )	Condition of Surfacing		S/U	1
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
<b>e</b> )	Whether free from defects such as visible cracks,		Yes/No	1
	exposed aggregates in case of CC Pa	vement		1
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	\
g)	Compaction of flank/slope & raincuts if any		Yes/No	$\nearrow$
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts		S/SRI/U	
	including its painting			
b)	Condition of Abutments & Wing w	alls, Slab in RCC	S/SRI/U	.
	culverts			
c)	Condition of railing/slab/approach	for bridges	S/SRI/U	
3.	Road Furniture			1/
a)	Whether sing board/informatory/c	autionary Board/	Yes/No	V
	Km & 200m stones/Pavement re			X
	provided and maintained			1
4.	Compliance History			
a)	Status of ATR's & any others			],, ,,-
		HOSKISHUGE	r tendor di	13 pessa

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	010010001000000
Unsatisfactory (U)	

Name: violit kumer singt

(Signature) 20

DESIGNATION:- A.E