FIELD INSPECTION REPORT

<u>TIEED INSTECTION REPORT</u>				
Date of Inspection: 03-12-2020 District: Fact of				ambaron
Division: RND Chalcic Length (Km): 1150,			ICM	
Name of the Road: Chalcia to Puranchlapra Road				1
Scheme/Programme : MAINTENANCE			Societies (Care	
Package No.: NA Road ID No.: 3170820				uala
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up Gradation/ Maintenance		
SI. No.	I. No. Parameters to be checked			Remarks
1,	Pavement			Remarks
a)	Road Junction condition			S
b)	Condition of Surfacing			2
c)	Riding Quality			٤
d)	Road Camber			2
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			70
f)	Contraction Joints provided or not (CC Pavement)			1
g)	Compaction of flank/slope & raincuts if any			-
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			-
c) .	Condition of railings/slab/approach for Bridges			_
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			No
4,	Compliance History			
a)	Status of ATR's & any	y others		
	_	Satisfactory (S) Satisfactory but requires Unsatisfactory (U)		SRI
Remember - In Some places 200 m stone formed.				

(Signature)

NAME:

DESIGNATION:

Jan 120