

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020 District: Nalanda
 Division : HARNAUT Length (km): 8.2 K.M
 Name of the Road: NODSARAI TO BRAGAN BIARA
 Scheme Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ✓
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

K. R. Singh
 03/12/2020
 (Signature)

NAME: Kishore Kumar Singh

DESIGNATION: A. E. NODSARAI