

FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020	District: N. Champaran	
Division: Naxalbar	Length (km): 6.70 Km	
Name of the Road: Bua P.W.D. to Ledihaqua		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/NAR/19/0016	Road Id No.: 31808802049	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance	Ongoing	
Sl. No.	Part to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☐
Unsatisfactory (U)	☐

B. Kumar
05/12/2020
(Signature)

NAME: BIPIN KUMAR

REDMI NOTE 9

DESIGNATION: JUNIOR ENGINEER