

# FIELD INSPECTION REPORT

Date of Inspection :	05-12-2020	District:	K1. Champauran
Division :	Naykatiagari	Length (km):	0.925 Km
Name of the Road:	Maldahia to Pokhara		
Scheme/Programme:	MAINTENANCE		
Package No.:	Rn/WF/NAR/19/0018	Road Id No.:	3180880205
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	<input checked="" type="checkbox"/>
Satisfactory but requires Improvement (SRI)	<input type="checkbox"/>
Unsatisfactory (U)	<input type="checkbox"/>

*B. Kumar*  
05/12/2020  
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: JUNIOR ENGINEER

REDMI NOTE 9

AI QUAD CAMERA