FIELD INSPECTION REPORT

Date of Inspection: 4-12-2020		District: W WAS CARAM.	
Division: 345MA-2.		Length (km): 937	
Name of the Road:		TO MANY POLA PONDA	
Scheme/Programme:			
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
THE PERSON NAMED IN COLUMN TWO		of Branding Prantecimies	

51. No.	Parameters to be checked	
1	Pavement and the second	Remark
a)	Road Junction condition	√s/u
b)	Condition of Surfacing	\S/U
c)	Riding Quality	US/U
d)	Road Camber	∨\$/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
1	Cross Drainage	· vielo
a)	Condition of head walls in Hume pipe culverts including its painting	\S/SRI/U
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts	\S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Vés/No
4.	Compliance History	的關鍵的
a)	Status of ATR's & any others	110.

Overall Rating

Satisfactory (S)	151
Satisfactory but requires Improvement (SRI)	162
Unsatisfactory (U)	

(Signature) 4.12.20

NAME: Engancordra Kusser Partey.

DESIGNATION: "T.E.