

FIELD INSPECTION REPORT

Date of Inspection :	4-12-2020	District:	W. Champaran
Division :	Bagaha 2	Length (km):	4.55 km
Name of the Road:	Sikta to Bagaha - Senra Road		
Scheme/Programme:	MAINTENANCE	M.R. 3054, new maint policy 2018.	
Package No.:	M.R.-N/19-Bagaha-1/051	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts <i>(work in prog)</i>	S/SRI/U
c)	Condition of railings/slab/approach for Bridges <i>(work in prog)</i>	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained <i>(work in prog)</i>	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others <i>work in prog</i>	No

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
4/12/20

NAME: Arvind Kumar
DESIGNATION: J. Eng