

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020 District: Nalanda
 Division: H/8 Length (km): 1.719 km
 Name of the Road: Ekangar Bihon Path to Bisai Bigha chaulanda Road
 Scheme Programme: MAINTENANCE

Parage No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Ongoing
 up gradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y/N
f)	Contraction Joints provided or not (CC Pavement)	Y/N
g)	Compaction of flank/slope & raincuts if any	Y/N
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y/N
4.	Compliance History	
a)	Status of ATR's & any others	

ongoing

Overall Rating :

Satisfactory (S) Satisfactory
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

3/12/2020
 (Signature)

NAME:

Ganesh Kumar Benjan

✓ B/RNG

For walpnr