

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020 District: Nalanda
 Division: 141/34 Length (km): 4.373 km
 Name of the Road: Ekangar Prihar Road to Alauwan Road
 Scheme/Programme: MAINTENANCE

Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Tip gradation/Maintenance

Ongoing
 Upgradation

Sl. No. Parameters to be checked Remarks

1. Pavement

a) Road Junction condition

b) Condition of Surfacing

c) Riding Quality

d) Road Camber

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No

f) Contraction Joints provided or not (CC Pavement) Yes/No

g) Compaction of flank/slope & raincuts if any Yes/No

2. Cross Drainage

a) Condition of head walls in Hume pipe culverts including its painting Satisfactory

b) Condition of Abutment & Wing walls, Slab in RCC culverts Satisfactory

c) Condition of railings/slab/approach for Bridges Satisfactory

3. Road Furniture

a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No

4. Compliance History

a) Status of ATR's & any others

End of

Overall Rating :

Satisfactory (S)

Satisfactory

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

3/12/2020

(Signature)

NAME: Gaurav Kumar Rana
 SE/R.M.D
 Pannalpur