FIELD INSPECTION REPORT

Date of Inspection : 03/11/2020 | District : Nalanda
Division : Hilsa | Length (km) : 0.554 km
Name of the Road : Hilsa Pattharu Road to Chaura
Scheme/Programme : MAINTENANCE
Package No. : | Road Id No. :
Status of the Project : Ongoing/Completed Under Maintenance
Work is a case of : New Connectivity Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Rating Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contruction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This work is new maintenance policy But NO Staten
Only Board
Tarun Kumar
Tarun Kumar
(Signature)
03/12/2

NAME :