

FIELD INSPECTION REPORT

Date of Inspection:	02-12-2020	District:	Nalanda
Division:	Hilsa	Length (km):	12.40 Km.
Name of the Road:	Karai Road to Sakinagar		
Scheme/Programme:	MAINTENANCE	Road Id No.:	
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		Ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance		upgradation.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Condition of flanks/slope & rainouts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SU/U
c)	Condition of railings/slab/approach for Bridges	S/SU/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/2m & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

work not done

work not done

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
02/12/20
(Signature)

NAME: