FIELD INSPECTION REPORT

		15		
Date of inspection .			District:	
Division	vision: Length (km): 2.90 kc			
Name of	the Road: Sa	to more to toke	ungsam ke kam li	dlar you
Scheme/	me of the Road: Sako More to Lohanigsam ke Ram We med Programme: MAINTENANCE Bows my			tak
Package	No.:	R	oad Id No.:	
	f the Project:	Ongoing/Completed/Ur	What was a second of the secon	
Work is	a case of:	New Connectivity/Up g	-	
SL No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign hoards/informatory/cautionary Board/km & 200m			Yes/No
4.	Compliance H	listory	That Early are	
a)	Status of ATR	s & any others		

Overall Rating:

Denformatory howed

fixed

Denth work in is close

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

SE SE

46 tights

(Signature)

NAME:

BEGIGNATION.