

FIELD INSPECTION REPORT

Date of Inspection : - 5/12/20		District: - Darchilanga.
Division : Biraoul		Length (km): 0.280/km.
Name of the Road: - Sako gawn Ke Ladle Khan STO Abdul Kyum Khan To		
Scheme/Programme: MAINTENANCE		200m je Ke ghar tak.
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others.	

This road is in ~~poor~~ Revised Estimate

Revised Estimate

Overall Rating :

This road is in ~~poor~~ Revised Estimate

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
5/12/20
JE

[Signature]
5/12/20
AE

(Signature)

NAME:

DESIGNATION: