FIELD INSPECTION REPORT

	Inspection:	Distri	District: MADHUBANI		
Division	HAYAE:	THR Length	Length (km): 4.600 km		
Name of	f the Road: 👂	PRAHI-CHOPAR TO R	AMPUR		
Package No.:		MAINTENANCE	CE		
		Road Id No.:			
Status of the Project:		Ongoing/Completed/Under Maintenance Work not start			
Work is	a case of:	New Connectivity/Up gradat	ion/ Maintenance	N. C. S.	
Sl. No.		Parameters to be check	æď	Remarks	
1.	Pavement				
a)	Road Junction condition			SAU	
b)	Condition of Surfacing			SAU	
c)	Riding Quality			SAU	
d)	Road Camber			S/J	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina				
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/Ú		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U		
c)	Condition of railings/slab/approach for Bridges		S/SRI/Ú		
3.	Road Furnitur				
a)	Whether sign stones/Pavemen	boards/informatory/cautionary t road markings are provided ar	Board/km & 200m and maintained	Yes/No	
4	Compliance Hi	ilory		Start of Discourse Acres	
10 10 10 10 10 10 10 10 10 10 10 10 10 1	Status of ATR's	400000000000000000000000000000000000000			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Sahder Chaud Lerry NAME:

DESIGNATION: T.E