## FIELD INSPECTION REPOR

Date of ]	inspection: 🔊		CHON REPORT		
Division	•	2/12/2020	District: Madhachani		
Name of	the Road:	agar	Length (km): 5:300 Ku		
Scheme/	Programme:	MAINTENANCE	3001-11		
Package	No.:	MAINTENANCE			
Status of the Project: Work is a case of:		Road Id No.:			
		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance			
Sl. No.	Maritan morther or	Parameters to	Allegantes and the second of th	TO THE PERSON OF THE PARTY.	
1.	Pavement			Remarks	
a)	Road Junction	Junction condition SAU			
b)	Condition of Surfacing			S/U	
c)	Riding Quality			-S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			-Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drains	ge			
a)	aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)			S/SRI/U	
b)				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniti	le:	Constitution of the consti		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No				
	Compliance 1				
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)		] ,.
Satisfactory but requires Improvement (SRI)		NA
Unsatisfactory (U)	/	
	$\mathcal{M}_{\mathbf{I}}$	
	(1)	-100
(6)	onature)	

NAME: Chambe Marken of h DESIGNATION: AIL