FIELD INSPECTION REPORT

Date of Inspection: 9/12/2020 Division: Jaynaga			Length (km): 275 KW	
Packag		MAINTENANCE		
			Road Id No.:	
	s a case of:	New Connectivity/Up 8	gradation/ Maintenance	I Mains
SI. No.	10 () had simply writers before to	Parameters to be	Harris Control of the	Remarks
1.	Pavement			Atoma, no
a)	Road Junction condition			
b)	Condition of Surfacing			S/U_
c)	Riding Quality			S/U
d)	Road Camber			S/U_
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	C	A	
a)	Condition of head walls in Hume pipe culverts including its painting			_S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U
3.	Road Carollure			
a) :	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance Hi	story	- K. (1805)	
a) S	Status of ATR's	& any others		Service of the service of the

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Dilip Kymar Symon DESIGNATION: J&