FIELD INSPECTION REPORT

Date of Inspection :			District: MADHUBANI		
Division: JAYNAWAR			Length (km): 4.400 km		
Name of the Road: PIPRHHI SE C		IPRAHI SE C			
	e/Programme:	MAINTENANCE			
Packag			Road Id No.: 31909708	020	
			ing/Completed/Under Maintenance Out of Maintenance		
Same and the last	A service and a resident of the service of the serv	New Connectivity/	Up gradation/ Maintenance		
SI. No.		Parameters to	o be checked	Remarks	
i.	Pavement	lent			
a)	Road Junction condition			SAF	
b)	Condition of Surfacing			SAU	
c)	Riding Quality			SAU	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes A do	
2.	Cross Drainage	AND DESCRIPTION OF THE PARTY OF	The state of the s		
	Condition of head walls in Hume pipe culverts including its painting			S/ŞRI/Ú	
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRIA	
	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furniture				
St	Whether sign boards/informatory/cautionary Board/km & 200m tones/Pavement road markings are provided and maintained Yes/No				
C	ompliance Hist	nr.			
St	atus of ATR's &	any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"
Unsatisfactory (U)	

(8 hum) 1917 03) 12/20

... (Signature)

NAME: Sahder churchary

DESIGNATION: