

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020 District: Nalanda
 Division H785 Length (km): 1.030 km
 Name of the Road: NH 110 Barinagar to Bihampur Margawan Road.
 Scheme/Programme: MAINTENANCE ✓
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Ongoing
 Work is a case of: New Connectivity/Up gradation/ Maintenance Up gradation

Sl. No.	Parameters to be checked	Re. Info
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
 3/12/2020

NAME: Gaurish Kumar Rayan
 S B / RWD
 Patna

Ongoing