

FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Maharashtra
Division:	Hill &	Length (km):	1.282
Name of the Road:	M. N. V. J. S. N. P. N.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A ✓
b)	Condition of Surfacing	N/A ✓
c)	Riding Quality	N/A ✓
d)	Road Camber	N/A ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Construction Joints provided as per (CC Pavement)	Yes/No N/A
g)	Compaction of flanks/slope & shoulders if any	✓/No/Yes
2.	Cross Drainage	
a)	Condition of head walls in House type culverts including its pointing	N/SRL ✓
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	N/SRL ✓
c)	Condition of railings/slab approach for Bridges	N/SRL ✓
3.	Road Furniture	
a)	Whether sign boards/informative/cautionary Board/kin & 200m across Pavement road markings are provided and maintained.	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	-
Satisfactory but requires improvement (SRI)	-
Unsatisfactory (U)	U

Inspector's Name

05.12.2020
(Signature)