

FIELD INSPECTION REPORT

Date of Inspection:	2.12.20	Division:	Naldemba
Division:	H.I.C.A	Length (km):	12.25
Name of the Road:	Pooja to Sulepur (2nd 4th)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Upgradation	

Sl. No.	Parameter to be checked	Remarks
1.	Pavement	
(i)	Road Junction condition	S
(ii)	Condition of Surfacing	S
(iii)	Finishing Quality	S
(iv)	Road Camber	S
(v)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
(vi)	Construction joints provided or not (CC Pavement)	Yes
(vii)	Composition of Bank/slope & minims if any	Yes
2.	Drainage	
(i)	Condition of head walls in U-type pipe culverts including its painting	S (21)
(ii)	Condition of Abutment & Wing walls, Slab in RCC culverts	S (19)
(iii)	Condition of wing/slab/approach for Bridges	S (23)
3.	Road Furniture	
(i)	Whether sign board/informative/cautionary Board/km A 200m mark/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
(i)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SMI)

Unsatisfactory (U)

Satisfactory

NAME Pradip Kumar Arora

Signature
Pradip Kumar Arora