

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 District: Nalanda
 Division: A-152 Length (km): 0.400 km
 Name of the Road: - PCC WORK IN APPROACH ROAD FROM PHASE 1 Jindaut
 Scheme Programme: MAINTENANCE ROAD NEAR BHANDARA MORE TO
 Package No.: Road Id No.: 240001
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation/ Maintenance

Sr. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SRI
b)	Condition of Surfacing	S
c)	Riding Quality	S/L
d)	Road Camber	S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/L
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/L
c)	Condition of railings/slab/approach for Bridges	S SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement and markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating :		
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

This Road is cross over all five year Maintenance

Taran Kumar

Taran Kumar
 (Signature) 03