

FIELD INSPECTION REPORT

Date of Inspection : 3-12-20	District: Nalanda
Division: 17122	Length (km):
Name of the Road: Repair of road Pirya to Salehpur (3rd division)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	upgradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	

ecwom
is not
prov'd

Walls in Hume pipe culverts including its painting	S/RT	S
ARC	S/RT	S
	S/RT	S

3.	Will the road be used for heavy traffic?	Yes
4.	Compliance History	
a)	State of the road	N.D

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

Satisfactory

NAME:

Pradeep Kumar Singh
J.C

3/12/20