

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Alaoda
Division :	ULISA	Length (km):	2.2 km
Name of the Road:	Aungmye to Gumbhar Road		
Scheme/Programme:	MAINTENANCE (1st year)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (1st year)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S SRI
b)	Condition of Surfacing	S SRI
c)	Riding Quality	S SRI
d)	Road Camber	U SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No - Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- NO -

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	U

ANJANE KUMAR
NAME:

Signature
(Signature)