FIELD INCOM

		SECTO MASEEC	TION DEDC-		
Date of]	nspection:	•	TION REPORT		
Division	Jainage	3.12.2020	District: Madherbani		
Name of	the Road:		Length (km): 1.100		
Scheme/	Programme:	Damu To	Bhogisaftpatti		
Package	No.:	MAINTENANCE	perper		
	the Project:	Onada 10	Road Id No.:		
Work is a case of:		New Completed	/Under Maintenance Tender	mocess	
SI. No.	and with a service on		p gradation/ Maintenance		
		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition				
b)				S/U	
	Condition of Surfacing			-S/U	
c)	Riding Quality			S/U	
d)	Road Camber			-S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No-	
2	Cross Drains	ge 11		100 - 5 - 5 - 5 - 7028	
a)	Condition of l	head walls in Hume p	ipe culverts including its painting	S/SRI/U	
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniti	ires.		Joseph C	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			-Yes/No	
	Compliance 1	i Story		the colores	
a)	Status of ATR	l's & any others	The state of the s	Alle alle file bearing and	

Overall Rating

Satisfactory (S)		_
Satisfactory but requires Improvement (SRI)	,	_
Unsatisfactory (U)	1	 _

NAME: SACHCHIDANAND SINHA
DESIGNATION: A E Basoporti