

FIELD INSPECTION REPORT

Date of Inspection: 04.12.20

District: RWD Bane

Thrust: Madhubani

Name of the Road:

Phulhar to Mangrahta

Scheme Programme:

ROAD INFRA

Package No.

Road Id No. 31910008041

Status of the Project:

Existing / completed Under Maintenance

Work is a case of:

New / Extension / Upgradation / Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surface?	✓
c)	Binding Quality	✓
d)	Road Carriageway	✓
e)	Whether free from holes / jacks or visible cracks exposed	✓
f)	Whether free from holes / jacks or visible cracks exposed	✓
g)	Whether free from holes / jacks or visible cracks exposed	✓
h)	Whether free from holes / jacks or visible cracks exposed	✓
2.	Cross Drainage	
a)	Condition of base width of drainage including its opening	✓
b)	Condition of drainage & flow with surface of road	✓
c)	Condition of drainage & flow with surface of road	✓
3.	Road Furniture	
a)	Whether sign boards / Informative / Advisory / Directional & other signs / Placards / road markings are provided and maintained	✓
4.	Compliance History	
a)	Status of A / B / C & any other	Not any

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

Inspector
04.12.20

Signature

NAME: Mr. Samir

DESIGNATION: J.E. RWD, Div. Banarhat

sect. Banarhat