FIELD INSPECTION REPORT

Date of	Inspection: C	4-12-2020	District: Samasting	40000	
Divisio	n: Patori	9 9	Length (km): 0.920KM		
		गरार शय के द्व	कान से दिनेश राय खें दिन	71 a Rue 14	
	e/Programme:	MAINTENANCE		R	
Package No.:			Road Id No.:		
			leted/Under Maintenance ity/Up gradation/ Maintenance		
		TO SEE SEE SEE SEE SEE SEE SEE SEE SEE SE		70-1945-5	
Sl. No.	Parameters to be checked			Remarks	
1.	Payement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			√s/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U-	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U)	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U /	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			NAA	

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04/12/2020

(Signature)

NAME: Asay kumar singh

DESIGNATION: J-E