## FIELD INSPECTION REPORT

Date of	Inspection : 2	112/2020	District: Samastibu	7	
Division: Daleinaheami			Length (km): 7.70 km		
Name of	the Road: Ra	mtegan sakan	ike ther se kalistia	n via you	
Scheme/Programme: MAINTENANCE			Policy PMS		
Package No.:			Road Id No.:		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance			
	a case or:	New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be checked Remarks			
1.	Pavement			The second secon	
a)	Road Junction	S/U S			
b)	Condition of Surfacing			s/u s	
c)	Riding Quality	S/U_S			
d)	Road Camber			s/u s	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No				
f)	Contraction Joints provided or not (CC Pavement)  Yes/No				
g)	Compaction of flank/slope & raincuts if any				
2.	Cross Drainag	ge i i i e i i i i i i i i i i i i i i i			
a)	Contraction Joints provided or not (CC Pavement)			S/SRI/U	
b)	Condition of A	S/SRI/U			
c)	Condition of ra	S/SRI/U			
3.	Road Dumiture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/N				
4.	Compliance H	istory			
a)	Status of ATR'	No			

Overall Rating

Satisfactory (S)			
Satisfactory but requires Impr	ovement (S	RI)	
Unsatisfactory (U)			

(Signature) J.

NAME: Mananjay prasad

DESIGNATION: J. E.