


# FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Begusarai
Division : TEUPHRA	Length (km): 3.39km
Name of the Road: PWD RD TO RAKHOUT	
Scheme/Programme:	MAINTENANCE
Package No.: RM/08/TEU/19/0010	Road Id No.: 32010502048
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing - Work in progress	— S/U
c)	Riding Quality — Work in progress	— S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	N.A.
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S) ✓	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
 03/12/2020  
 (Signature)

NAME: UMESHA KUMAR MAHTO  
 DESIGNATION: JUNIOR ENGINEER