

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Begusarai
Division : TSCMRA		Length (km): 2.400 km
Name of the Road: From Baahwara chattr to Tada		
Scheme/Programme: MAINTENANCE		
Package No.: RM/02/TSCMRA/0009		Road Id No.: 32010601010
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition — Done in progress	S/U
b)	Condition of Surfacing — Patches done in progress	S/U
c)	Riding Quality — do —	S/U
d)	Road Camber — do —	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. — do —	Yes/No
f)	Contraction Joints provided or not (CC Pavement) — do —	Yes/No
g)	Compaction of flank/slope & raincuts if any — do —	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	N.R.
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	✓	(S)
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: UMESH KUMAR MAHTO

DESIGNATION: JUNIOR ENGINEER

h
AD
31/12/20