

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Begusarai
Division : TEDHRA		Length (km): 2.800 KM
Name of the Road: Ground for Mohanpur RDO Road to Timmahan Rly, Guma		
Scheme/Programme: MAINTENANCE		
Package No.: PM/BE/T&I/19/0005		Road Id No.: 32010502103
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. B.T. Work done	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement) B.T. Work done	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	M-R
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S) ✓	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Grn 03/12/2020
(Signature)

h
Adm
31/12/20

NAME: UMESH KUMAR MAHTO
DESIGNATION: JUNIOR ENGINEER