FIELD INSPECTION REPORT

Package N Status of Work is a Sl. No.	rogramme: No.: MR-N/8 the Project:	Length (km): 1.20 K.M. aidfus Chandasi Path to Sahora ville MAINTENANCE Lelz-Leffatra os Road Id No.: OneMay (Completed/Under Maintenance)	lage.
Package N Status of Work is a Sl. No.	rogramme: No.: MR-N/8 the Project:	Roll - 20 fatra os Road Id No.:	lage,
Package N Status of Work is a Sl. No.	rogramme: No.: MR-N/8 the Project:	Roll - 20 fatra os Road Id No.:	
Status of Work is a Sl. No.	the Project:		
Work is a		Ong Mng/Completed/Under Maintenance	
Sl. No.	case of:	tus of the Project: Ongoing/Completed/Under Maintenance	
rational and the			Remarks
1000	Parameters to be checked		Remarks
	Pavement		
a)	Road Junction condition		S/U M
b)	Condition of Surfacing		S/U N
c)	Riding Quality		S/U N
d)	Road Camber		S/U
~)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No /
f)	Contraction Joints provided or not (CC Pavement)		Yes/No /
g)	Compaction of flank/slope & raincuts if any		Yes/No ↑
2.	Cross Drainag	e jan	
a) (Condition of head walls in Hume pipe culverts including its painting		s/sri/u ,
b) (Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c) (Condition of railings/slab/approach for Bridges		S/SRI/U
3. I	Road Furnitur	C	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No		Yes/No
4.	Compliance History		
a) S	Status of ATR's & any others		NO.
Overall Ra	ating .	Surface Work Remaining,	11)
Overall iva	•	Satisfactory (S)	\$
	-	Satisfactory but requires Improvement (SRI) Unsatisfactory (U)	

NAME: Jai Brakach Surph,
DESIGNATION: J.E.

Scanned with CamScanner

(Signature)