

# FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Begusar
Division :	Balia	Length (km):	1.750
Name of the Road:	Nanghat dhala Se Katarimala yadav sala tak path		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	32010608078
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <del>N/A</del>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <del>N/A</del>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <del>N/A</del>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

05.12.20  
Executive Engineer  
(Signature)  
RWD Works Division, Balia

NAME: Ramshree Chaudhary

DESIGNATION: Executive Engineer