

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nalanda
Division :	HILSA	Length (km):	1.026 km
Name of the Road:	Hilsa - Ekangar Main road to dhanbar village (upto dhanbarson Pol. house)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/Y
b)	Condition of Surfacing	S/Y
c)	Riding Quality	S/Y
d)	Road Camber	S/Y
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	=
Unsatisfactory (U)	=

NAME: NITAND KUMAR

(Signature)
02/12/20