

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020 District: Aurangabad
 Division : Aurangabad Length (km): 6.50 km
 Name of the Road: Eraka Buthwa Road

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.: 10602808122

Status of the Project: Ongoing/Completed/Under Maintenance ✓

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	Spot surface damage S/U
c)	Riding Quality	S/U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & cutouts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	200m Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Sunil Kumar
 3/12/2020
 (Signature)

NAME: