


FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	Nolanda
Division :	H 2189	Length (km):	1.60km
Name of the Road:	Asharki to Khaddi		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	NO ATR
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	



Samsung Quad Camera
Shot with my camera

Ram
03.12.2020
J.E.
(Signature)

NAME: Ram Pat Choudhary