

# FIELD INSPECTION REPORT

Date Of Inspection 02.12.2020		District Bhojpur
Division Piro		Length (km):
Name of the Road:	Repair of Road from Janka puria Pul to Enradpur Bihula Canal	
Scheme/Programme	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance ✓	
Work is a case of :	New, Connectivity/Up gradation/Maintenance ✓	
SI No.	Parameters to be checked	Remarks
1	<b>Pavment</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Name: Raja Om Prakash  
Designation Executive Engineer

(Signature)  
02/12/2020