

FIELD INSPECTION REPORT

Date of Inspection: - 03.12.20		District: - Kishanganj	
Division: - Kishanganj-I		Length(km): 13.20	
Name of the Road: - Repair of road from Kathamatho to Tappu (Part-II)			
Scheme/Programme:		MAINTENANCE	
Package No.: - N/A		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance (construction under progress)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		
a)	Road Junction Condition	} N/A	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N/A		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	} N/A	Yes/No
g)	Compaction of flank / slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting - N/A		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		} N/A
c)	Condition of railings/Slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained - N/A		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others - N/A		

Overall Rating : - N/A

Satisfactory(S)	---
Satisfactory but requires Improvement (SRI)	---
Unsatisfactory(U)	---

Remarks - Road is being constructed under PMGSY-II

NAME: Er. Radheshyam prajapati


 D.L. 03.12.20
 R.W.D (W) Division
 Kishanganj-1