

## FIELD INSPECTION REPORT

Date of Inspection: 4/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 1.600 km	
Name of the Road: Repair of Road from Kailash chawak Bali chukla Road			
Scheme/Programme: MAINTENANCE		Tairusa Seseowadi Tola	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance (Taken up in PMGSY-II)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	S/U
a)	Road Junction Condition	Taken up PMGSY-II
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints Provided or not ( CC Pavement)	NA
g)	Compaction of fland / shop & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

  
 (Signature)

NAME:

AE