


## FIELD INSPECTION REPORT

<b>Date of Inspection:</b> 4/12/2020		<b>District:</b> Kishanganj	
<b>Division:</b> Kishanganj-1		<b>Length(km):</b> 1.200 km	
<b>Name of the Road:</b> Repair of Road from Thauwpara Jharbari to Baingachi			
<b>Scheme/Programme:</b> MAINTENANCE			
<b>Package No.:</b>		<b>Road Id No.:</b> 21205806076	
<b>Status of the Project:</b>		Ongoing/Completed /Under Maintenance (Taken up in PMGSY-II)	
<b>Work is a case of:</b>		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	S/U
a)	Road Junction Condition	Taken up in PMGSY-II } NA
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	Yes/No } NA
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U } NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA } Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No ATR

**Overall Rating :**

<b>Satisfactory(S)</b>	NA
<b>Satisfactory but requires Improvement (SRI)</b>	-
<b>Unsatisfactory(U)</b>	-

  
 4/12/20  
 (Signature)

**NAME:**

AE