

## FIELD INSPECTION REPORT

Date of Inspection: 4/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 9.50 km	
Name of the Road: Repair of Road from Belwa to Ramganj			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance (Taken up in PMGSY-II)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	S/U
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

  
 (Signature)  
 AE

NAME: