

## FIELD INSPECTION REPORT

Date of Inspection: 5/12/2020		District: Kishangangj
Division: Kishangangj - I		Length(km):
Name of the Road: Repair of Road from Nagri to Bahikal via Makraha		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 20205808079
Status of the Project:		Ongoing/Completed /Under Maintenance
Work is a case of:		New Connectivity/ Up gradation / Maintenance

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	✓S/U
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints Provided or not ( CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	-

  
 (Signature)  
 AE

NAME: