FIELD INSPECTION REPORT Date of Inspection: 05 12 2020 District: Kishanganj Division: Kishanganj-1 Length(km): 3.40 km Repair of Road from Chepra Bakhari to Bishanpur Haat Name of the Road: Scheme/Programme: MAINTENANCE Package No.: 21205 8080 87 Ongoing/Completed /Under Maintenance Hander over to R.C.D. Status of the Project: Work is a case of: New Connectivity/ Up gradation / Maintenance Remarks \$1. No Parameters to be checked S/U 1. **Pavement** Transfer to R. C.D.

alignment D.B. so Road, S/U **Road Junction Condition** a) S/U b) **Condition of Surfacing Riding Quality** c) S/U **Road Camber** d) S/U e) Whether free from defects such as visible cracks, exposed aggregates Yes/No in case of CC Pavement. NA f) Contraction Joints Provided or not (CC Pavement) Yes/No g) Compaction of fland / shop & raincuts if any Yes/No 2. **Cross Drainage** Condition of head walls in Hume pipe culverts including its Painting a) S/SRI/U b) S/SRI/U Condition of Abutment & Wing walls, slab in RCC culverts NA Condition of railings/Slab/approach for Bridges c) S/SRI/U 3. **Road Furniture** Whether sign boards/informatory/cautionary Board/km & 200m a) Yes/No stones/Pavement road markings are provided and maintained NA **Compliance History** 4. Status of ATR's & any others a) NOATA tending Overall Rating:

Satisfactory(S) Satisfactory but requires Improvement (SRI) Unsatisfactory(U)

(Signature)

AE

NAME: