		FIELD INSPEC	CTION REPORT	
Date of 1	Inspection :	04-12-2021	District: Godgan]	Sec. 1
Division	: R-WD-	Gopalgam-1	Length (km):	
	the Road:	Bhoptabur	to Mechia Jalabi	17
Scheme/Programme: MAINTENANCE			•	
Package			Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Payement			
a)	Road Junction condition			š/u (3)
b)	Condition of Surfacing			S/U (U)
c)	Riding Quality			S/U (U)
d)	Road Camber			S/U (S)
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			YesNo Raveled
f)	Contraction Joints provided or not (CC Pavement)			Yes/No YUL
g)	Compaction of flank/slope & raincuts if any			Yes/No NO TOUNCO
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			s/sri/u 🖒
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U HA

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

**Overall Rating** 

3.

a)

4.

a)

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Ajoy Kumorr Tiworoi

Road Furniture

**Compliance History** 

Status of ATR's & any others

:

DESIGNATION: Quecutive Engineers

Yes/No

(Signature)