FIELD INSPECTION REPORT

Date of Inspection: o	4/12/2020	District: Gobalgant
21.4.4	lgant-1	Length (km): 10.50
Name of the Road:	Sasamusa to Haz	Sharper Via manihasa
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Complete	d/Under Main chance
Work is a case of:	New Connectivity/	Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	\8/U	
b)	Condition of Surfacing	VS/Ú	
c)	Riding Quality	VS/Ū	
d)	Road Camber	\ 8/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/Nov	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	V8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Vs/SRI/U	
c)	Condition of railings/slab/approach for Bridges	\S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO. AS	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Ajoy, kumon Tiwari DESIGNATION: Executive Engineer

(Signature)